

Date 2 August 2023

Photo 1.



Brittle failure of main fork showing a pocket of decay and degraded wood tissue.

Photo 2.



Snapped limb through brittle wood tissue, with mark of fruiting body at main fork and fruiting body on grass nearby.

Photo 3.



Image of the end of the snapped out main limb showing the cubicle nature of cell structure through *Inonotus hispidus* degradation.

Photo 4.



Position of limb failure in tree.